



*This Technical Advisory describes an issue which may or may not affect the customer's product*

# Intel Technical Advisory

TA-0844-1

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

October 18, 2006

## Some AXXUSBFLOPPY kits shipped with incorrect cables

*Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The AXXUSBFLOPPY may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.*

### Products Affected

AXXUSBFLOPPY

### Description

Some AXXUSBFLOPPY kits have shipped with a USB cable (PN: 6017B0054201) that is approximately one inch too short for use in the SR1500 Intel® Server Chassis. The short cable has a revision of A01. The longer cable that is necessary for the SR1500 has a revision of A02. Both the A01 and A02 cables will successfully fit in the SR2500 chassis. Below is a picture of the longer A02 cable.



### Corrective Action / Resolution

All inventory of the revision A01 cables have been purged and all AXXUSBFLOPPY kits have been screened for the correct cable. All future AXXUSBFLOPPY kits will ship with the proper cable included. If you have purchased a kit with the short USB cable and would like a replacement, contact Intel using your normal warranty process. Please indicate that you are calling regarding TA# 0844 and have the part number of the USB cable available (6017B0054201).

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division  
Intel Corporation